


INSTRUCTIONS FOR USE



Certified Hygrometer and
Temperature Indicator

Analog Humidity/Temperature Instruments

These wall-hung instruments can simply be read directly.
Clean with a damp cloth and polish dry.

Yearly calibration is recommended.

This can be accomplished by:

1. Adjusting them to a known standard.
2. Returning them to us for calibration.
3. Sending them to testing laboratory for calibration.